Document 3 Quadrennial survey

	Flag pole and stone bollards.		
Front wall to Close	The eastern wall containing the entrance gate is brick-built with a brick-on-edge coping. This wall returns along one side of the parking apron.	The southern section of the wall has a recently repaired crack – see EXT(19 The northern section of the wall is cracked as a result of the proximity of a nearby Cherry tree – see EXT(23). The gate pier on the N side of the forecourt entrance has some cracking in the joints, likely due to rusting and expansion of the embedded iron gate hinge – see EXT(20)	Seek advice from an arboriculturist regarding the value of the tree and whether to replace. Allow for taking down and rebuilding this section of wall once the need to remove the tree has been agreed.

DRAFT