



George Hotel – Room 111 defective post – 11.09.25



Top of lower post



Lower and upper post junction with cross rail



Head plate to left of top post



Head plate to right of top post

George Hotel – Room 111 defective post – 11.09.25



Beam over bar area



Modern end support post butted against brick pier



Failed roof support framing above bar beam