



Photographs x 2 Doorway blocked
up within exterior house wall and
within exterior corridor leading to
a courtyard and house entrance.





Photograph to show proposed window location within new lobby area.