

View to the site from North East

As can be seen from this photo the polytunnel will not be visible from this direction due to the existing tree line and the slope on the site.



Key

- 1. Existing Barn
- 2. Existing Glasshouse
- 3. Proposed Polytunnel



Existing Trees





View to the site from the North

As can be seen here, the Existing barn and greenhouse are barely visible beyond the tree line. As the polytunnel will be further down a slope from these buildings, it will not be visible at all from this direction.

Key

1. Existing Barn
2. Existing Glasshouse
3. Proposed Polytunnel



Existing Trees




View of site from the West

The Polytunnel will be further away and further down a slope than the existing barn, and therefore should be barely visible behind the trees even in winter. In summer, and in the future when more trees have grown in the hedgerow area, it will be further obscured.

Key

1. Existing Barn
2. Existing Glasshouse
3. Proposed Polytunnel



View to the site from East South East



Key

1. Existing Barn
2. Existing Glasshouse
3. Proposed Polytunnel




Existing Trees



This photo is taken at close range from within the applicants own field. Yet even from this angle it is clear that the polytunnel will be obscured by the current hedge and trees, and this will increase as the hedgerow grows.

View to the site from the South East



Key

1. Existing Barn
2. Existing Glasshouse
3. Proposed Polytunnel



Existing Trees



This photo is taken from the entrance gate to the site where the public may have a view to the polytunnel but it is clear from this angle that it will be obscured by existing hedgerow.