

Tottenham House

STABLES EXISTING FLOOR FINISHES

20.02.2025

CONTENTS

This document contains floor scans and location on plan for the following rooms within the Old Stables at ground floor level:

G01 - Office
G02 - Harness Room
G03 - Lobby
G04 & G05 - Stalls
G06 - Stalls
G07 - Tack Room
G08 & G10 - Lobby & Store
G09 - Wash Down Room
G11 - Lobby/Stairs
G12 - Stalls
G13 - Stalls
G14 - Former Stalls
G15 - Lobby
G16 - Kitchen
G17 - Lobby
G18 - Store
G19 - Bathroom
G20 & G21 - Former Coach Houses
G22 - Former Coach House
G23 - Office
G24 - Stalls
G25 - Passage
G26 - Stalls
G27 - Lobby/Stairs

INTRODUCTION

The lifting and storage of the ground floor finishes was undertaken in two main stages, the initial stage of rooms are believed to include G16, G17 and G19, which was undertaken by Gardiner & Theobald when they were running the project and are all recorded as G17. The second stage of lifting was undertaken by Traditional Stone Restoration Limited for Size Group.

The cobble stones are Granite, and both the flagstones and thresholds are York Stone, all (except G11) have been lifted and recorded and are now in safe storage in several buildings, as listed in the accompanying information, supplied by Traditional Stone Restoration Limited.

Please note that the pallets are in sequential order, with the number of pallets related to the stages of lifting. Therefore, there is a break in the numbering of the pallets, being 1-175 and 201-234.

Copyright © ADAM Architecture 2025. All rights reserved. No part of this publication may be reproduced or transmitted, in any form or by any means, without prior permission in writing from the Author.

G01 - Office



KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G02 - Harness Room




KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G03 - Lobby




KEY

- | | |
|---|---|
|  | Absent/Removed |
|  | Flagstone flooring - generally fair/poor condition |
|  | Flagstone carved to mimic stone sets |
|  | Stone Sets internal - generally very poor condition |
|  | Stone Sets external - generally very poor condition |
|  | Brick Pavious - generally very poor condition |
|  | Stone threshold present - generally fair/poor condition |
|  | Modern Concrete - generally poor condition |
|  | Post 1950 additions |

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G04 & G05 - Stalls





KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviments - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G06 - Stalls




KEY

- | | |
|---|---|
|  | Absent/Removed |
|  | Flagstone flooring - generally fair/poor condition |
|  | Flagstone carved to mimic stone sets |
|  | Stone Sets internal - generally very poor condition |
|  | Stone Sets external - generally very poor condition |
|  | Brick Pavious - generally very poor condition |
|  | Stone threshold present - generally fair/poor condition |
|  | Modern Concrete - generally poor condition |
|  | Post 1950 additions |

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G07 - Tack Room



KEY

-  Absent/Removed
-  Flagstone flooring - generally fair/poor condition
-  Flagstone carved to mimic stone sets
-  Stone Sets internal - generally very poor condition
-  Stone Sets external - generally very poor condition
-  Brick Paviers - generally very poor condition
-  Stone threshold present - generally fair/poor condition
-  Modern Concrete - generally poor condition
-  Post 1950 additions

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G08 & G10 - Lobby & Store



- KEY**
- Absent/Removed
 - Flagstone flooring - generally fair/poor condition
 - Flagstone carved to mimic stone setts
 - Stone Setts internal - generally very poor condition
 - Stone Setts external - generally very poor condition
 - Brick Paviours - generally very poor condition
 - Stone threshold present - generally fair/poor condition
 - Modern Concrete - generally poor condition
 - Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G09 - Wash Down Room



KEY

- | | |
|---|---|
|  | Absent/Removed |
|  | Flagstone flooring - generally fair/poor condition |
|  | Flagstone carved to mimic stone sets |
|  | Stone Sets internal - generally very poor condition |
|  | Stone Sets external - generally very poor condition |
|  | Brick Pavious - generally very poor condition |
|  | Stone threshold present - generally fair/poor condition |
|  | Modern Concrete - generally poor condition |
|  | Post 1950 additions |

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G11 - Lobby

Flagstones in-situ at time of compiling this document



KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G12 - Stalls



KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G13 - Stalls



KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G14 - Former Stalls




KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G15 - Lobby

PLEASE NOTE: Concrete floor - no image.



KEY

-  Absent/Removed
-  Flagstone flooring - generally fair/poor condition
-  Flagstone carved to mimic stone setts
-  Stone Setts internal - generally very poor condition
-  Stone Setts external - generally very poor condition
-  Brick Pavours - generally very poor condition
-  Stone threshold present - generally fair/poor condition
-  Modern Concrete - generally poor condition
-  Post 1950 additions

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G16 - Kitchen

PLEASE NOTE: Polycam image absent. The lifting of this floor was undertaken by Gardiner & Theobald, with no recording being identified.



KEY

-  Absent/Removed
-  Flagstone flooring - generally fair/poor condition
-  Flagstone carved to mimic stone sets
-  Stone Sets internal - generally very poor condition
-  Stone Sets external - generally very poor condition
-  Brick Paviers - generally very poor condition
-  Stone threshold present - generally fair/poor condition
-  Modern Concrete - generally poor condition
-  Post 1950 additions

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G17 - Lobby

PLEASE NOTE: Polycam image absent. The lifting of this floor was undertaken by Gardiner & Theobald, with no recording being identified




KEY

- | | |
|---|---|
|  | Absent/Removed |
|  | Flagstone flooring - generally fair/poor condition |
|  | Flagstone carved to mimic stone sets |
|  | Stone Sets internal - generally very poor condition |
|  | Stone Sets external - generally very poor condition |
|  | Brick Paviments - generally very poor condition |
|  | Stone threshold present - generally fair/poor condition |
|  | Modern Concrete - generally poor condition |
|  | Post 1950 additions |

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G18 - Store

PLEASE NOTE: Concrete floor - no image.




KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviments - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G19 - Bathroom

PLEASE NOTE: Polycam image absent. The lifting of this floor was undertaken by Gardiner & Theobald, with no recording being identified.



KEY

-  Absent/Removed
-  Flagstone flooring - generally fair/poor condition
-  Flagstone carved to mimic stone sets
-  Stone Sets internal - generally very poor condition
-  Stone Sets external - generally very poor condition
-  Brick Paviers - generally very poor condition
-  Stone threshold present - generally fair/poor condition
-  Modern Concrete - generally poor condition
-  Post 1950 additions

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G20 & G21 - Former Coach Houses



KEY

-  Absent/Removed
-  Flagstone flooring - generally fair/poor condition
-  Flagstone carved to mimic stone sets
-  Stone Sets internal - generally very poor condition
-  Stone Sets external - generally very poor condition
-  Brick Paviers - generally very poor condition
-  Stone threshold present - generally fair/poor condition
-  Modern Concrete - generally poor condition
-  Post 1950 additions

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G22 - Former Coach House



KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G23 - Office



KEY

- | | |
|---|---|
|  | Absent/Removed |
|  | Flagstone flooring - generally fair/poor condition |
|  | Flagstone carved to mimic stone sets |
|  | Stone Sets internal - generally very poor condition |
|  | Stone Sets external - generally very poor condition |
|  | Brick Pavious - generally very poor condition |
|  | Stone threshold present - generally fair/poor condition |
|  | Modern Concrete - generally poor condition |
|  | Post 1950 additions |

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G24 - Stalls

PLEASE NOTE: Polycam
image absent. Not
received from
TRADITIONAL STONE
RESTORATION LTD



KEY

- | | |
|---|---|
|  | Absent/Removed |
|  | Flagstone flooring - generally fair/poor condition |
|  | Flagstone carved to mimic stone sets |
|  | Stone Sets internal - generally very poor condition |
|  | Stone Sets external - generally very poor condition |
|  | Brick Pavious - generally very poor condition |
|  | Stone threshold present - generally fair/poor condition |
|  | Modern Concrete - generally poor condition |
|  | Post 1950 additions |

PLEASE NOTE: Floor
scans are the work of
TRADITIONAL STONE
RESTORATION LTD.
Pages have been assembled
by ADAM using their
information.

G25 - Passage



KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G26 - Stalls




KEY

- Absent/Removed
- Flagstone flooring - generally fair/poor condition
- Flagstone carved to mimic stone setts
- Stone Setts internal - generally very poor condition
- Stone Setts external - generally very poor condition
- Brick Paviours - generally very poor condition
- Stone threshold present - generally fair/poor condition
- Modern Concrete - generally poor condition
- Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.

G27 - Lobby



- KEY**
- Absent/Removed
 - Flagstone flooring - generally fair/poor condition
 - Flagstone carved to mimic stone setts
 - Stone Setts internal - generally very poor condition
 - Stone Setts external - generally very poor condition
 - Brick Paviours - generally very poor condition
 - Stone threshold present - generally fair/poor condition
 - Modern Concrete - generally poor condition
 - Post 1950 additions

PLEASE NOTE: Floor scans are the work of TRADITIONAL STONE RESTORATION LTD. Pages have been assembled by ADAM using their information.