



①
Flint knapped and coursed, with one course of brick below the coping. Two bands of brick, each of two courses with alternating headers and stretchers, roughly dividing the wall into thirds.



④
The middle band of brick ends before an area of brick repair, vertically alternating between stretchers and headers, and interrupting the flintwork.

Note:
Flintwork to be carried out by a suitably experienced flint worker.



②
An area of brick repair interrupting the flintwork, slightly slanted.



⑤
The lower band of brick continues here. Above, a pattern of brick and coursed flint, in a bungaroosh style. One course of brick below stone coping.



③
See area 1.



⑥
Either side of the gateposts, brick quoins and coursed knapped flint. Next to the house, a band of brick in two courses centrally.

S3 SUITABLE FOR REVIEW AND COMMENTS

Revisions:	P1	Initial Issue	15/01/2026
	P2	Planning Issue	30/01/2026

PROJECT: Bulford Manor Wall
SHEET: Flint and Brickwork Front Elevation

This drawing is ©copyright Pritchard Architecture 2025. No dimensions to be scaled from this drawing except for planning purposes

DRAWING NO: V1013 - PRA - ZZ - XX - DR - A - 30011
SCALE: NTS @A3

REV: P2

DATE: January 2026

PRITCHARD
ARCHITECTURE
Porters Lodge, College Road
HM Naval Base, Portsmouth, P01 3LJ
email: studio@pritchardarchitecture.co.uk