

Hilmarton Manor - Sample Panel Photographs

LBC ref. PL/2024/10022



Photograph showing sample panel on-site with mortar.



Photograph showing sample panel with existing ha-ha wall.



Photograph showing close-up of the wall indicating that it appears to be a dry wall with gaps that are too small to mortar.