


Stonekraft Restoration
1-3 Chichester Park
Westbury
Wiltshire
BA13 3AN

Mr H Bhayani
c/o 36 - 41 Hill Steet Court

Trowbridge
BA14 8LB



Spalling on left widow head
Can be repaired filled in with stonedust lime mortar if you wish.



As discussed before the right hand stone cill is decayed and needs replacing :- A
also right side jamb:-B, centre jamb :-C & right window head :-D