

Existing window surround showing Bath stone deterioration associated with historic cement-based pointing and patch repairs, and further damage to the sill and lintel

