

Supporting Images - Former Fence and Boundary Context

These photographs support the retrospective planning application by showing the previous timber fence, its approximate overall height, its collapse, the former outside boundary condition as seen from the road, and the replacement fence being installed alongside the collapsed boundary.

Contents

1. Former timber fence - close-up measurement showing the approximate overall height of the previous fence.
2. Former timber fence - wider measurement view showing the previous fence at approximately 2.2 to 2.35 metres in overall height.
3. Former fence collapse - photograph showing the previous boundary in a failed and dangerous condition.
4. Former fence collapse - wider view of the previous boundary after collapse.
5. Former outside boundary visible from the road.
6. Former outside boundary visible from the road, overgrown with ivy, thorn bushes and blackthorn.
7. Former outside boundary visible from the road and roadside boundary context.
8. Photograph showing the replacement fence being installed alongside the collapsed former timber boundary fence, illustrating the condition of the previous enclosure and the circumstances in which the replacement works were undertaken.

Image 1



Former timber fence - close-up measurement showing the approximate overall height of the previous fence.

Image 2



Former timber fence - wider measurement view showing the previous fence at approximately 2.2 to 2.35 metres in overall height.

Image 3



Former fence collapse - photograph showing the previous boundary in a failed and dangerous condition.

Image 4



Former fence collapse - wider view of the previous boundary after collapse.

Image 5



Former outside boundary visible from the road.

Image 6



Former outside boundary visible from the road, overgrown with ivy, thorn bushes and blackthorn.

Image 7



Former outside boundary visible from the road and roadside boundary context.

Image 8



Photograph showing the replacement fence being installed alongside the collapsed former timber boundary fence, illustrating the condition of the previous enclosure and the circumstances in which the replacement works were undertaken.