


## Front – South facing Elevation

Rotten wooden windows with blown double glazed units will be replaced.

Next door neighbour.  
They have  
Standard  
UPVC  
windows.




Bay window was replaced with flush casement upvc in 2022 as the wooden windows were badly deteriorated and were not secure.

Rotten wooden windows with blown double glazed units will be replaced.

Side – East facing Elevation

Wooden windows will be replaced.




Wooden window will be replaced with French doors as shown in drawings.



Wooden door will be replaced with composite door as per application.

## Rear – North facing Elevation

Rotten single glazed windows were replaced with flush casement upvc windows in 2021. They looked home made. One didn't open at all and the other only had a small opening which would not allow an escape route in the instance of an emergency.



Wooden window will be replaced.

Rotten wooden window was replaced as part of the kitchen refurbishment in 2022. See next page for notes.

## Rear – North facing Elevation



Conservation roof lights were added as part of the kitchen refurbishment in 2022. See notes on bi-fold doors for additional information.

Rotten wooden toilet window (behind tree) will be replaced.

10

Two wooden windows were replaced with bi-fold doors as part of the kitchen refurbishment in 2022. The conservation officer was consulted, and a pre-planning check was submitted and response received. Work was carried out under permitted development rights which were confirmed to be intact. Work was signed off through building control.