

PHOTOGRAPHIC RECORD - BEFORE, DURING AND AS CONSTRUCTED

90 Stratford Road, Salisbury, SP1 3JS



BEFORE - front garden prior to the works, showing lawn/soft landscaping and the existing concrete pedestrian path.



DURING WORKS - geotextile membrane, hardstanding formation, timber retaining work, fence posts and central steps/path.



AS CONSTRUCTED - central stone steps/path and the pedestrian opening through the transverse timber fence.



AS CONSTRUCTED - wide view from the hardstanding showing the transverse fencing, pedestrian opening and retained magnolia.



AS CONSTRUCTED - hardstanding/parking area and 900 mm timber fencing.



AS CONSTRUCTED - additional view of the permeable Cotswold buff stone hardstanding and timber fencing.