





An illustration of the Chapel dating to shortly after the Nave was rebuilt in 1855




Current photo



Roof gully










Approximate position of
the new lead overflow pipe

Removal, repairs and reinstallation of the tower Northside window in the clockroom







Removal, repairs and reinstallation
of the tower Northside window in
the clock room





Removal, repairs and reinstallation of the tower Westend window in the clock room







Replace Tower spiral staircase glass




Spiral Staircase resurfacing of x 7 treads due to wear




Westend stained-glass window mesh




Westend stained-glass window mesh





Southside stained-glass window mesh



Cleaning of moss and lichen



Cleaning of moss and lichen



Cleaning of moss and lichen



Cleaning of moss and lichen



Cleaning of moss and lichen



Cleaning of moss and lichen



Cleaning of moss and lichen



Cleaning of moss and lichen



Cleaning of moss and lichen



Repairs to the lead bell rope shoot



Repairs to the lead bell rope shoot




Continued repainting of the downpipes



Continued repainting of the downpipes




Porch Gutters and down pipes



New porch
gutters
connect to the
cast iron Nave
downpipes

Chapel path repointing



Chapel path repointing



Chapel path repointing

