

Principal elevation



Rendering to right hand section only, (not including porch)



Condition of existing render is very poor, cement render, historically patched and repair and now cracked, spalling and debonding



Condition of existing render is very poor, cement render, historically patched and repair and now cracked, spalling and debonding