

1. View of existing garage and compost enclosures as viewed from the south corner of the site



2. View of the rear elevation of the existing garage, lean-to store area and compost bins



3. View of garage structure from the southeast of the site. Photograph shows existing trees ad hedgeline



4. View of east elevation



5. View of garage from northeast corner



6. View of garage from the driveway to the northwest



7. View of the front elevation of the garage



8. View of the existing lean-to store area to the east of the existing garage