
KEY

- Temp Roadway (Plastic)
- Temp Roadway (Aluminium)
- Stone Road or Bellmouth (New)
- Stone Road (Upgrade)
- Tree/Veg/Hedgerow Clearance
- New Fenceline
- Silt Fencing
- New Gate
- New Culvert
- Temp Bridge
- GS6
- Argo / Tractor / Haugland Access
- Wash Bays
- CDM Work Area Boundry
- Scaffolding



Site Hazards — Risk Rating: Medium

Steep camber on Low Side of Tower.

Bridleway on high side of tower

Environmental Hazards — Risk Rating: Medium

Monitoring of badger Sett recorded within ditch adjacent to pylon with motion censored cameras over a three week period. If the sett is confirmed as active and the works are likely to damage the sett or cause badger disturbance a licence from Natural England will be required.

Ditch that runs through the trees adjacent to the pylon had very little water present and no submerged vegetation present, unlikely to support breeding GCN. No GCN surveys required.

Vegetation clearance will be undertaken in accordance with the relevant sections of the Standard Environmental Mitigation Method Statement (SEMMS) for Breeding Birds.

Emergency Details

Closest Hospital:	Salisbury District Hospital
What3Words Location:	///tragedy.boxing.drizzly

Drawn: DD	nationalgrid
Checked OPS:	
Checked Enviro:	
YYM 95 & 96	REV: 1

Balfour Beatty