

Following the recent information provided, I understand that the works have already been carried out, however there is no clarity as to the methods and materials used for the installation on the headwall, therefore I still would like to have 3 years monitoring by an independent qualified Arboriculturalist.

Kind regards,

Kate

Kate Tate

Arboricultural Officer

Planning Technical Services