


Tree Elements
39 High St
Steeple Ashton
Trowbridge
BA14 6EU



Tree report for St Marys Church, Church St, Steeple Ashton, BA146EW.

Tree 1. Robinia – Growing closest to church.

Recommended work - Lightly prune back church side branches of tree to provide clearance – Remove any major deadwood.

Tree 2. Robinia – Growing close to perimeter wall.

Recommended work – This tree is in a unsuitable position and is damaging the church wall which has already previously been repaired, I recommend fell/removing tree and grinding out the stump to prevent regrowth then replanting a more suitable tree for the position.

Tree 3 – Robinia –

Recommended Work – Remove any major deadwood/Conservation deadwood.

Tree Elements
39 High St
Steeple Ashton
Trowbridge
BA14 6EU



Tree Elements
39 High St
Steeple Ashton
Trowbridge
BA14 6EU

