

DATE: 9 February 2026
DESIGNER: DFL-UK (JM)
PROJECT No: 3420-DFL-ELG-XX-LD-EO-13002
PROJECT NAME: Southview Farm



Indicative light spill diagram.
> Not for construction.
> Initial light levels shown.
> Light spill diagram does not consider blocking or shading effects of light limiting objects and represents worst-case horizontal light spill at ground floor level.
> Light spill diagram to be read in conjunction with Lighting Strategy: 3420-DFL-ELG-XX-RP-EO-13001-S3


Isolux contours shown:
5.0 Lux - Red
1.0 Lux - Blue
0.4 Lux - Purple
0.2 Lux - Yellow

Outdoor Lighting Report

PREPARED BY: DFL-UK
+44 (0)1962 855080
17/18 City Business Centre
Winchester Hants
SO23 7TA
e-mail: info@dfi-uk.com
website: www.dfi-uk.com

Horizontal Illuminance (lux)

Light Spill -



Illuminance (lux)

Ecology Receptor 001

0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

Results

Eav	0.00
Emin	0.00
Emax	0.00
Emin/Emax	0.00
Emin/Eav	0.00

Illuminance (lux)

Human Receptor 001

[illegible]

Results

Eav	0.00
Emin	0.00
E _{max}	0.01
Emin/E _{max}	0.00
Emin/Eav	0.00

Illuminance (lux)

Ecology Receptor 002


[illegible]

Results

Eav	0.00
Emin	0.00
E _{max}	0.03
Emin/E _{max}	0.00
Emin/Eav	0.00

Illuminance (lux)

Human Receptor 002 #1



Results

Eav	0.17
Emin	0.00
Emax	0.76
Emin/Emax	0.00
Emin/Eav	0.00

Illuminance (lux)

Human Receptor 002 #2

0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.0	0.0	0.0	0.0	0.0	0.0	0.0

Results

Eav	0.01
Emin	0.00
Emax	0.02
Emin/Emax	0.14
Emin/Eav	0.43