



F03 Fireplace

Late C18 carved, moulded and painted mantle surround with modern ceramic tile battered slips, much cracked.

Cast iron, fluted and part rusted frame with fire brick linings.

There is a raised plain brick plinth.

There is evidence of a former, plain bolection moulded surround that partly exists behind but now over-built. It would match that in F.02.

Proposed Works:


Remove the ceramic tile slips.

Ensure the flue is cleaned and not blocked.

Make good any loose brickwork.

Install new ceramic tile slips to the the choice of the Cathedral Close surveyor.

Cast iron components to be cleaned, sanded and given 2 coats of heat-proof black paint.



Title : **17 Cathedral Close Salisbury SP1 2EB**

Drawing : **Detail Specifications for repair works to:**

Hearth and Mantle - F03

Revisions : Rev Date

Scale : NTS

Drawn : CP

Date : December 2025

Drawing No.

1306.D.17