



Proposed Works:

Ensure the flue is cleaned and not blocked.

Make good any loose brickwork.

Cast iron components to be cleaned, sanded and given 2 coats of heat-proof black paint.

Remove the later mantle shelf and make good the surround to match existing.

S.02 Fireplace.

C18 stone bracketed, eared moulded surround. Panelled battered stone linings. Plain chamfered kerb. Raised, tiled inner hearth. Floral patterned ceramic over slip. Cast iron frame with fire brick lining

There is evidence of a former oak bressumer over and behind.



Revisions : Rev Date

Scale : NTS
Drawn : CP
Date : December 2025

Drawing No.

1306.D.20

Drawing : Detail Specifications for repair works to:

Fireplace - S.02