



Existing roof trusses with metal tie rods and purlins between. Rafters over. Timber battens with double Roman tiles hooked over. Ceiling joists below, no ceiling currently. All roof timbers to be retained, splice repair made if required. Structural engineer to inspect the roof



Roof timbers showing signs of woodboring insect attack. All existing timbers to be treated

