



Historic Wall Condition Appraisal – Gateway Adjacent to 207 Boreham Road, Warminster
Photograph Sheet



Gateway relative to 207 Boreham Road – from Boreham Road (south)



Gateway relative to 207 Boreham Road – from Boreham Road (south)

Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772



Gateway from Boreham Road (south)



Gateway relative to 207 Boreham Road (left) – from field (north)

Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772





Gateway relative to 207 Boreham Road – from field (north)



Gateway head – from road (south)


Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772



West jamb

Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772





East jamb

Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772



Upper wall thickness reduction (west side from field)



Coping condition – looking west

Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772





Wall face – road side (east jamb)



Brick facing to
field face of wall

Wall face – field side (west jamb)

Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772





Gate and hinge arrangement– from road side

Ladysmith House, High Street
Tisbury, Salisbury, Wiltshire, SP3 6LD
Telephone: 01747 870772

