

Jonathan Foster.

L.C. Foster & Sons.

Master Thatchers since 1889

2 Lower Wyke Cottages, Andover, SP11 6AN



Ash Tree Cottage
Easton Royal
Pewsey
Wilts

11th May 2026

To whom it may concern.

Regarding the existing window on the rear elevation. The pitch of this window is not suitable for thatch as the angle of the above it too shallow. For thatch to shed water off properly the pitch needs to be at a minimum of 42 degrees to the horizontal.

Jonathan Foster.