

INTERNAL PHOTOGRAPHS

PURTON HOUSE CHURCH END PURTON

25-168

Refurbishment & Repairs

James Slater & Company
19 Dyer Street
Cirencester
Glos.GL7 2PP
Tel: 01285 650686
Email: reception@jameslater.co.uk

July 2026

Contents

Key 4

Bedroom 1 5

Bedroom 2 7

Bedroom 4 9

Bedroom 5 11

Rev.	Date	Status	Purpose of Issue	Author	Checked
A	17/07/2026	D5	Issued to support application for listed building consent	BDR	

Architectural floor plan of a five-bedroom apartment. The plan shows five bedrooms, each with a bed and bedside table. There are two bathrooms, a kitchen area, and a living area. The layout includes various furniture pieces like sofas, armchairs, and a dining table. The plan is labeled with room names and dimensions.

Rooms and Dimensions:

- BEDROOM 1: S0.76 H2.35
- BEDROOM 2: S0.76 H2.33
- BEDROOM 3: S0.75 H2.33
- BEDROOM 4: S0.75 H2.33
- BEDROOM 5: S0.40 H2.00
- BATH 1: S0.75 H2.35
- BATH 2: S0.75 H2.33
- KITCHEN: S0.75 H2.33
- LIVING: S0.75 H2.33
- DINING: S0.75 H2.33
- HALL: S0.75 H2.33
- CL. 1: S0.75 H2.35
- CL. 2: S0.75 H2.33
- CL. 3: S0.75 H2.33
- CL. 4: S0.75 H2.33
- CL. 5: S0.75 H2.33
- CL. 6: S0.75 H2.33
- CL. 7: S0.75 H2.33
- CL. 8: S0.75 H2.33
- CL. 9: S0.75 H2.33
- CL. 10: S0.75 H2.33
- CL. 11: S0.75 H2.33
- CL. 12: S0.75 H2.33
- CL. 13: S0.75 H2.33
- CL. 14: S0.75 H2.33
- CL. 15: S0.75 H2.33
- CL. 16: S0.75 H2.33
- CL. 17: S0.75 H2.33
- CL. 18: S0.75 H2.33
- CL. 19: S0.75 H2.33
- CL. 20: S0.75 H2.33
- CL. 21: S0.75 H2.33
- CL. 22: S0.75 H2.33
- CL. 23: S0.75 H2.33
- CL. 24: S0.75 H2.33
- CL. 25: S0.75 H2.33
- CL. 26: S0.75 H2.33
- CL. 27: S0.75 H2.33
- CL. 28: S0.75 H2.33
- CL. 29: S0.75 H2.33
- CL. 30: S0.75 H2.33
- CL. 31: S0.75 H2.33
- CL. 32: S0.75 H2.33
- CL. 33: S0.75 H2.33
- CL. 34: S0.75 H2.33
- CL. 35: S0.75 H2.33
- CL. 36: S0.75 H2.33
- CL. 37: S0.75 H2.33
- CL. 38: S0.75 H2.33
- CL. 39: S0.75 H2.33
- CL. 40: S0.75 H2.33
- CL. 41: S0.75 H2.33
- CL. 42: S0.75 H2.33
- CL. 43: S0.75 H2.33
- CL. 44: S0.75 H2.33
- CL. 45: S0.75 H2.33
- CL. 46: S0.75 H2.33
- CL. 47: S0.75 H2.33
- CL. 48: S0.75 H2.33
- CL. 49: S0.75 H2.33
- CL. 50: S0.75 H2.33
- CL. 51: S0.75 H2.33
- CL. 52: S0.75 H2.33
- CL. 53: S0.75 H2.33
- CL. 54: S0.75 H2.33
- CL. 55: S0.75 H2.33
- CL. 56: S0.75 H2.33
- CL. 57: S0.75 H2.33
- CL. 58: S0.75 H2.33
- CL. 59: S0.75 H2.33
- CL. 60: S0.75 H2.33
- CL. 61: S0.75 H2.33
- CL. 62: S0.75 H2.33
- CL. 63: S0.75 H2.33
- CL. 64: S0.75 H2.33
- CL. 65: S0.75 H2.33
- CL. 66: S0.75 H2.33
- CL. 67: S0.75 H2.33
- CL. 68: S0.75 H2.33
- CL. 69: S0.75 H2.33
- CL. 70: S0.75 H2.33
- CL. 71: S0.75 H2.33
- CL. 72: S0.75 H2.33
- CL. 73: S0.75 H2.33
- CL. 74: S0.75 H2.33
- CL. 75: S0.75 H2.33
- CL. 76: S0.75 H2.33
- CL. 77: S0.75 H2.33
- CL. 78: S0.75 H2.33
- CL. 79: S0.75 H2.33
- CL. 80: S0.75 H2.33
- CL. 81: S0.75 H2.33
- CL. 82: S0.75 H2.33
- CL. 83: S0.75 H2.33
- CL. 84: S0.75 H2.33
- CL. 85: S0.75 H2.33
- CL. 86: S0.75 H2.33
- CL. 87: S0.75 H2.33
- CL. 88: S0.75 H2.33
- CL. 89: S0.75 H2.33
- CL. 90: S0.75 H2.33
- CL. 91: S0.75 H2.33
- CL. 92: S0.75 H2.33
- CL. 93: S0.75 H2.33
- CL. 94: S0.75 H2.33
- CL. 95: S0.75 H2.33
- CL. 96: S0.75 H2.33
- CL. 97: S0.75 H2.33
- CL. 98: S0.75 H2.33
- CL. 99: S0.75 H2.33
- CL. 100: S0.75 H2.33

Bedroom 1

Wall A



Wall B



Wall C



Wall D



Ceiling



The coving is not original, and neither is the ceiling rose. The ceiling rose is not central of the room. Both the coving and the ceiling rose are the result of an interior design makeover of the 1980's, with the items purchasable from a local DIY store of its day. The ceiling rose is poorly fitted to the ceiling with visible screws present. The fixing of the light fitting is reliant on the electrical wiring to hold it to the ceiling.


As well as providing support to the light fitting the remainder of the electrics has been added as and when required resulting in exposed wiring and boxed fittings, all of which currently detract from the appearance of the room but more importantly offer a great risk to the safe operation of the room as the wiring is not even covered in trunking but left exposed with insufficient clips to adequately retain the cables securely against the walls.

Bedroom 2

Wall A



Wall B



Wall C



Wall D



Ceiling



Two light fittings to this room neither of which are centrally located & and considering the current location of sanitary fittings, is a disaster waiting to happen with regard to the proximity of live electrical wiring and water.

Bedroom 4

Wall A



Wall B



Wall C



Wall D



Ceiling



Four recessed halogen style light fittings to this room.

Bedroom 5

Wall A



Wall B



Wall C



Wall D



There is clear 'scarring' to this room of previous changes to it's layout.