


Permission To Dig			
PTD URN	Job number	Name	
614479698_PTD1621070826	AVSS5600773	Jeoff Gillham	
Drill through floors ?	Drill through external walls ?	Hoist (vehicle) to deploy on customer premises ?	Use exist
NO	NO	NO	
Any other reason ?	Provide details	Customer Name	House
NO		Jeoff Gillham	
Town	Address Postcode	Customer representative	
Westbury	BA13 4SW	Steve Gibson	
I confirm that the work to be carried out has been explained to the customer / tenant / landowner ?	Does the customer / tenant / landowner wish to be present when the work is carried out ?	Date	
YES	YES	2026-08-07 00:00:00	
Photos			

Description:	TREE CUTTING SS1RAH77	Project Code:	992JN	Estimate No:		Page No:	2 OF 9
Planner:	CHLOE LEADBETTER	Planner Tel No:	08000232450	Plan OUC:	BVK764	Supp Code:	80180320
Doc Title:	Job Notes	Exchange:	BRATTON	COW:	OR	Issued:	15/08/2026
Certified By:		Certifier Tel No:		Company/OUC:		Job Type:	
						Certified Date:	

Description:	TREE CUTTING SS1RAH77	Project Code:	992JN	Estimate No:		Page No:	3 OF 9
Planner:	CHLOE LEADBETTER	Planner Tel No:	08000232450	Plan OUC:	BVK764	Supp Code:	80180320
Doc Title:	Job Notes	Exchange:	BRATTON	COW:	OR	Issued:	15/08/2026
Certified By:		Certifier Tel No:		Company/OUC:		Job Type:	
						Certified Date:	

Supplier	Excavate on private property ?
Openreach	NO
ing hole for cable ?	Prune branches or cut trees ?
NO	YES
e name / number	Street
	Westcott
UIN	Customer Signature
514479698	

Description:	TREE CUTTING SS1RAH77	Project Code:	992JN	Estimate No:		Page No:	5 OF 9
Planner:	CHLOE LEADBETTER	Planner Tel No:	08000232450	Plan OUC:	BVK764	Supp Code:	80180320
Doc Title:	Job Notes	Exchange:	BRATTON	COW:	OR	Issued:	15/08/2026
Certified By:		Certifier Tel No:		Company/OUC:		Job Type:	
						Certified Date:	

Description:	TREE CUTTING SS1RAH77	Project Code:	992JN	Estimate No:		Page No:	6 OF 9
Planner:	CHLOE LEADBETTER	Planner Tel No:	08000232450	Plan OUC:	BVK764	Supp Code:	80180320
Doc Title:	Job Notes	Exchange:	BRATTON	COW:	OR	Issued:	15/08/2026
Certified By:		Certifier Tel No:		Company/OUC:		Job Type:	
						Certified Date:	


Description:	TREE CUTTING SS1RAH77	Project Code:	992JN	Estimate No:		Page No:	7 OF 9
Planner:	CHLOE LEADBETTER	Planner Tel No:	08000232450	Plan OUC:	BVK764	Supp Code:	80180320
Doc Title:	Job Notes	Exchange:	BRATTON	COW:	OR	Issued:	15/08/2026
Certified By:		Certifier Tel No:		Company/OUC:		Job Type:	
						Certified Date:	

Description:	TREE CUTTING SS1RAH77	Project Code:	992JN	Estimate No:		Page No:	8 OF 9
Planner:	CHLOE LEADBETTER	Planner Tel No:	08000232450	Plan OUC:	BVK764	Supp Code:	80180320
Doc Title:	Job Notes	Exchange:	BRATTON	COW:	OR	Issued:	15/08/2026
Certified By:		Certifier Tel No:		Company/OUC:		Job Type:	
						Certified Date:	

Description:	TREE CUTTING SS1RAH77	Project Code:	992JN	Estimate No:		Page No:	9 OF 9
Planner:	CHLOE LEADBETTER	Planner Tel No:	08000232450	Plan OUC:	BVK764	Supp Code:	80180320
Doc Title:	Job Notes	Exchange:	BRATTON	COW:	OR	Issued:	15/08/2026
Certified By:		Certifier Tel No:		Company/OUC:		Job Type:	
						Certified Date:	

A55 Reference	I3AX45N		
A55 Type	Tree Cutting,Traffic Management,		
Engineer's EIN	601676062	OUC	BVK616
Engineer's Name	Rob,Warriner	Estimate No.	
Email Address	robert.warriner@openreach.co.uk		
Phone No	07918722174		
Job number	SS1RAH77	Circuit No.	SGEA91703154,FBSS0197676

MAP



Location Details			
Exchange Name	Bratton	Exchange District	SS
Reason for work	Access to overhead network - cabling to restore customer service		
Temporary Clear	N		

Site Address	The Butts, Westbury, BA13 4SW		
1141 code	BRX	Postal Code	BA13 4SW
Traffic Management Required?	Y	Service affected	Y

Summary of Work	
Job Summary	Joint meet with TM rd closure, tree cutting and SD hoist to erect new drop wire from dp to property. Tree cutting required around pole and line of sight needed to property. This is in a conservation area so this will need to be taken into account. Tm as pole is a D and will need to be accessed by hoist.
General Notes	Joint meet with TM rd closure, tree cutting and SD hoist to erect new drop wire from dp to property. Tree cutting required around pole and line of sight needed to property. This is in a conservation area so this will need to be taken into account. Tm as pole is a D and will need to be accessed by hoist.

Traffic Management			
Are you working on Provision or Repair task?	Repair		
Type of Traffic Management	Road Closure		
Suspension Type		Width of road (m)	2
Width of obstruction?	2	Site length (m)	10
Type of Vehicle	Hoist	Type of road	Single C/W without footpath
Speed of road	30 mph	Volume of traffic	Light
Approach Bends OnSite	No	Estimated duration required	12, 0
Is it essential to have vehicles within the work onsite?	Y	Traffic Management operative required onsite?	Y
Are work at junction?	N	Bus Stop Suspension	N
Parking bay suspension	N	Are there side roads within 200m?	N
Footpath Closure	N	Cycle paths	N
Entrances or exits	Y	>Existing permanent traffic lights	N

<i>School(s)</i>	N	<i>999 Services?</i>	N
<i>Additional hazards or obstacles?</i>	N	<i>Level Crossing</i>	N
<i>Pavements</i>	N	<i>Pedestrian Crossings?</i>	N
<i>Bus lane/red routes?</i>	N	<i>Is this Traffic management request suitable for an on the N day response?</i>	
<i>Laybys</i>	N	<i>Text for additional Hazards</i>	
<i>Easting</i>	391433	<i>Northing</i>	152245
<i>Permission to work reference</i>			
<i>Have you completed a permission to work form on PTW app ?</i>		<i>Have you left a permission to work paper form with the customer/land owner?</i>	
<i>Enter name, address and contact number of customer</i>			

Photo(s) of Problem TrafficManagement
--





10:24

4:06

5.5m or more

2.5m or more

Less than 2.5m

Traffic Control Method:

TTRO Road closure

⚠ Consult your supervisor, manager or competent person

Carriageway • No • 30mph or less • No • No • No • Less than 2.5m

robert.wariner@openreach.co.uk • • 14/08/2025 10:24:44

While the Red Book (and extracted content within this web app) provides guidance, it cannot cover every situation and a site specific risk assessment should be undertaken for all works sites. Where a risk assessment identifies that measures are needed in addition to those required by the Code, these must be implemented.

Please feedback any issues or anomalies that you identify to patrick@pjkeary.co.uk

 slg.pjkeary.net

<

>

+





Tree Cutting

Who owns the tree?	Private	What tree cutting is required?	Pole and span
Number of span(s) to be cleared	1	Joint user pole(s)?	N
DP number	5	Reason / notes	
Number of pole(s) to be cleared	1	Are There Access Restrictions?	N
Carrier Pole Number		Consent / contact details required	
Engineer joint meet required?		Tree Owner Address	The wilderness, The Butts, BA13 4SW, Westbury
Contact number	07825071288	Email address	Unknown
Easting	391432	Northing	152281
Permission to work reference	614479698 PTD1621070826		
Have you completed a permission to work form on PTW app ?	Y	Have you left a permission to work paper form with the customer/land owner?	
Enter name, address and contact number of customer			

Photo(s) of Problem TreeCutting
--



