

10. Church Street

Tree Schedule

Tree No	Species	Height	Dia @ 1.5m	Crown Spread		Vitality	Observations	Hazard Assessment Recommendations & Year 1	Grade	Management Recommendations	Year			
											2	3	4	5
0840	Ash <i>Fraxinus excelsior</i>	12	200 250	2	Early Mature	Good	Divides at ground level. Swept heavily north east. Swamped in dead & live Ivy. Fallen dead hung up Ivy clad Elm tree in canopy.	Fell dead Elm Kill Ivy Clear off dead Ivy.	1 1 1					
0841	Sycamore <i>Acer pseudoplatanus</i>	10	250	3	Semi Mature	Good	Dense Ivy	Kill Ivy	3					
0842	Common Lime <i>Tilia x europaea</i>	12	800	4	Mature	Average	Previously pollarded at 7m. Ganoderma brackets 0-1m. <i>Kretzschmaria deusta</i> at base west side, audibly hollow surrounding. Epicormic growth trimmed. Light & power attached.	Re-pollard Monitor	1 3					
0843	Common Lime <i>Tilia x europaea</i>	10	600	4	Mature	Good	Previously pollarded at 7m, dense regrowth. Basal epicormic growth. Light & power attached.			Control basal epicormic growth				X
0844	Common Lime <i>Tilia x europaea</i>	11	750	4	Mature	Good	Previously pollarded at 8m, vigorous regrowth. Visible strip of decay 6 - 8m/pollard point. Light & power attached.			Re-pollard		X		
0845	Common Lime <i>Tilia x europaea</i>	10	450	3	Early Mature	Good	Previously pollarded at 8m, vigorous regrowth. Basal epicormic growth.			Control basal epicormic growth				X
0846	Common Lime <i>Tilia x europaea</i>	11	650	4	Mature	Good	Previously pollarded at 8m, vigorous regrowth. Basal epicormic growth.			Control basal epicormic growth				X
0847	English Oak <i>Quercus robur</i>	18	700	5	Mature	Average	Ivy killed. Swept east.							

10. Church Street

Tree Schedule

Tree No	Species	Height	Dia @ 1.5m	Crown Spread		Vitality	Observations	Hazard Assessment Recommendations & Year 1	Grade	Management Recommendations	Year			
											2	3	4	5
0848	Sycamore <i>Acer pseudoplatanus</i>	15	380	6	Early Mature	Good	Ivy killed							
0849	Common Lime <i>Tilia x europaea</i>	15	800	3	Mature	Good	Previously pollarded at 8m. Multiple ganoderma brackets 0 - 2.5m. Steel cable bolted to and wrapped around tree trunk. Light & power attached.	Re-pollard	1					
0850	Common Lime <i>Tilia x europaea</i>	16	800	4	Mature	Good	Previously pollarded at 8m							
G0851	Species inc. Sycamore, Leylandii, Goat Willow, Elder, Common Lime & Yew	4 - 12	100 - 300	2 - 6	Early Mature	Good	Block of secondary woodland between churchyard & Abbey access. Limited footfall. Dense Ivy. Patches of squirrel damage,							
	3 x Ash <i>Fraxinus excelsior</i>	ave 10	ave 300	1	Early Mature	Dead	Neighbouring trees - dead & within falling distance of scout seating area	Fell (contact landowner)	2					

10. Church Street - Site Sketch Plan

