


existing solid masonry walls, red brick with rubble infill

failed / missing / damaged stone plinth course & facing brick below

low garden level




EXISTING WALL PLINTH DETAIL

repointing with matching lime mortar

new bathstone ashlar plinth course with matching lime mortar bed and perp joints

new stone slabs, mortar bedded on compacted hardcore

new localised brck base reclaimed from elsewhere onsite with matching lime mortar bed and perp joints



PROPOSED WALL PLINTH DETAIL

1:5

0

0.025

0.05

0.075

0.10

0.125

ISSUED FOR PLANNING

CLIENT	Mr & Mrs Morgan
PROJECT	Penleigh Farmhouse
DRWG TITLE	Wall Plinth Details
DRWG NO	A17 25 37 P3003
DRAWN	NB
SCALE	1:5 @ A3
DATE	04.09.26
CHK'D	NB

atelier 17 ltd

Atelier 17 Ltd, 28 Southleigh, Bradford On Avon, BA15 2EQ

nigel.a.w.bedford@gmail.com

www.atelier17.co.uk

T: 07841679591

This drawing is copyright. Only figured dimensions to be used.

Contractors to check all dimensions before proceeding