LEVEL MONITORING

for Subsidence Management Services

Jones House, Bradford-on-Avon, BA15 2EE

Client:	Subsidence Management Services
Client Contact:	Ian Domigan
Claim Number:	4501979544
Client Reference:	IFS-AVI-SUB-22-0100930
Policy Holder:	Mr and Mrs Rod and Barbara Pudduck
Report Date:	27 June 2023
Our Ref:	M18904

SubsNetUK

Level Monitoring Readings


The following table shows the reading levels of the various Level Monitoring Station points.


Date	1	2	3	4	5	6	7	8	9	10
05/01/2023	10.2565	10.2404	10.1744	10.0979	9.9041	9.2970	9.3084	8.6602	8.0118	8.0163
23/02/2023	10.2568	10.2358	10.1693	10.0987	9.9046	9.2974	9.3073	8.6563	8.0063	8.0121
21/04/2023	10.2534	10.2306	10.1635	10.0948	9.9014	9.2931	9.3026	8.6508	7.9996	8.0057
26/06/2023	10.2519	10.2275	10.1609	10.0899	9.2982	9.2901	9.3002	8.6471	7.9977	8.0025

Date	11	12	13	14
05/01/2023	10.1690	10.1435	10.1195	10.1117
23/02/2023	10.1655	10.1416	10.1183	10.1111
21/04/2023	10.1594	10.1369	10.1134	10.1057
26/06/2023	10.1579	10.1339	10.1101	10.0996


Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.






SubsNetUK



1000.0
500.0
0.0
-500.0
-1000.0
Difference in Reading (mm)
01/23
02/23
04/23
06/23
Site Visit Date
11
12
13
14

SubsNetUK

Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.





FRONT

SubsNetUK

SubsNetUK

Site Visit Notes

Deep datum in place.