Transport Planning Associates

A Planning Application by

SPRING DEV 08 LIMITED

In respect of

Purton Landfill Solar, WILTSHIRE

Pre-Construction Highway Condition Survey

June 2023



Document Management

© 2023 Transport Planning Associates Limited. All Rights Reserved.
This document has been prepared by Transport Planning Associates for the sole use of our client in accordance with generally accepted consultancy principles, the budget for fees and the terms of service agreed between Transport Planning Associates and our client. Any information provided by third parties and referred to herein has not been checked or verified by Transport Planning Associates, unless otherwise expressly stated in the document. No third parties may rely upon this document without the prior and express written agreement of Transport Planning Associates.

Document Review

	Status	Author	Checker	Approver	Date
01	Draft	AG	RR	JD	29 | 06 | 23
-	Issue				
A	Revision[a]				
B	Revision[b]				

Issued by:

Bristol
Cambridge
London
Oxford
Welwyn Garden City

Transport Planning Associates
25 King Street
Bristol
BS1 4PB

0117 925 9400
bristol@tpa.uk.com
www.tpa.uk.com

[a]
[b]

Contents

Page

1 Introduction 1
2 Methodology 2
3 Pre-Condition Survey Results 3

List of Figures

Figure 2.1 Agreed Survey Extent

List of Appendices

Agreed Study Area
A Westbound Survey Photos
B Westbound Survey Map of Existing Defect Locations
C Eastbound Survey Photos
D Eastbound Survey Map of Existing Defect Locations

1 Introduction

1.1 This report has been prepared by Transport Planning Associates (TPA), on behalf of Spring Dev 08 Limited, and summarises a visual pre-construction highway condition survey of the highway network in the vicinity of the recently permitted solar farm development located at Purton Landfill, Wiltshire (PL/2021/10405).

1.2 This visual pre-condition survey has been prepared to satisfy point 'xv' of Condition 7 of the planning permission. This states the, as part of the detailed Construction Traffic Management Plan (CTMP), there is a requirement for:

> *"A photographic pre-commencement highway condition survey carried out along Mopes Lane".*

1.3 This report sets out the pre-commencement condition, to support the detailed CTMP and discharge Condition 7 of the planning permission. A repeat walkover survey will be completed by TPA prior to construction commencing to confirm that this condition survey remains an accurate representation of the existing highway condition. This will be sent to officers at Wiltshire Council prior construction commencing.

2 Methodology

2.1 The extent of the pre-construction condition survey was agreed with officers at Wiltshire Council prior to the survey being undertaken. A map showing the survey extent is shown on **Figure 2.1**.

2.2 The survey was conducted along an 800m section of Mopes Lane, from its junction with the Cricklade Road to the east, to the Site access. The survey was carried out by Alexander Grundy of TPA on 28th June 2023.

2.3 Mopes Lane comprises a single carriageway two-way road along the length of the survey extent. The survey was conducted in two halves, with the southern side of the carriageway inspected by walking west from the Cricklade Road junction to the Site, followed by the northern half of the carriageway inspected by walking east from the Site to the Cricklade Road junction. Existing highway defects were identified and noted at the chainage point on the survey route.

2.4 The purpose of the pre-construction condition survey is to assess the baseline condition of the adopted highway, prior to construction commencing. A post-construction condition survey will then be completed, and comparisons made to see whether any additional highway defects are evident, that can be attributed to construction activities.

3 Pre-Condition Survey Results

3.1 The identified existing highway defects that were identified are within this section. The surveyed route displayed signs of surface wear throughout, with specific defects identified in the below tables.

3.2 The existing defects identified along the southern side of the Mopes Lane carriageway, starting at the Cricklade Road junction and terminating at the site access, are set out in **Table 3.1** below. The respective photos are included as **Appendix A** and a map showing the existing defect locations is included as **Appendix B**.

Table 3.1 Existing Highway Defects on Southern Side of Mopes Lane (Westbound Walkover)

Chainage (m) – From Cricklade Road / Mopes Lane Junction to Site Access	Identified Defect	Photo ID
0	Cracking at Junction and white lines faded	001
9	Fracturing	002
28-33	Edge of carriageway deterioration and fracturing	003-004
39-61	Edge of carriageway deterioration and fracturing	005-006
69	Fracturing	007
73	Patching in middle of carriageway	008
75	Patching in middle of carriageway	009
81	Patching at speed bump/ramp	010
87	Patching in middle of carriageway	011
109	Fracturing/Cracking	012
123	Fracturing/Cracking	013
143	Fracturing/Cracking	014
155	Fracturing/Cracking	015
185	Fracturing/Cracking	016
199	Fracturing/Cracking	017
225	Fracturing/Cracking	018
248	Fracturing/Cracking	019
255	Fracturing/Cracking	020
258	Patching in middle of carriageway	021
261	Speed bump traverses carriageway	022

265	Fracturing/Cracking and Patching in middle of carriageway	023
271-278	Fracturing/Cracking at edge of carriageway	024-025
312-337	Fracturing/Cracking and Patching	026-028
340	Fracturing and patching on speed bump/ramp	029
341	Patching in middle of carriageway	030
343-353	Fracturing and potholing in the middle of carriageway	031-032
357-377	Fracturing in the middle of the carriageway	033-035
387-413	Fracturing	036-037
420-431	Fracturing, potholing and carriageway deterioration	038-039
436	Fracturing	040
442	Patching at speed bump/ramp	041
503	Fracturing	042
535	Patching	043
558	Edge of carriageway deterioration	044
570-600	Edge of carriageway deterioration and fracturing	045-048
601	Fracturing	049
622	Fracturing	050
634	Speed bump/ramp	051
637	Patching	052
642-656	Edge of carriageway deterioration and fracturing	053-054
663	Fracturing	055
669	Fracturing	056
681	Fracturing	057
685	Fracturing	058
690	Fracturing traverses carriageway	059
715	Fracturing	060
728	Potholing and edge of carriageway deterioration	061
734	Potholing	062
737	Patching	063

755	White lines faded at gate	064
759	Fracturing	065
768-808	Fracturing and potholing on new surfacing	066-068
820	Utility trench traverses carriageway and fracturing	069
829	Fracture crack on concrete surface traverses carriageway	070
830	Patching, fracturing and potholing by site access road/junction and utility trenching at mopes lane/site access road junction	071
834	Patching, fracturing and potholing on site access road	072

3.3 The existing defects identified along the northern side of the Mopes Lane carriageway, starting at the site access and terminating at the Cricklade Road junction, are set out in **Table 3.2** below. The respective photos are included as **Appendix C** and a map showing the existing defect locations is included as **Appendix D**.

Table 3.2 Existing Highway Defects on Northern Side of Mopes Lane (Eastbound Walkover)

Chainage (m) – From Site Access to Cricklade Road / Mopes Lane Junction	Identified Defect	Photo ID
0	Patching, fracturing and potholing by site access road/junction and utility trenching at mopes lane/site access road junction	001
15	Fracturing	002
19	Fracturing	003
30	Fracturing	004
39	Fracturing	005
46	Fracturing and utility trenching traverses carriageway	006
48-57	Fracturing	007-008
74-80	Fracturing and utility trenching traverses carriageway	009
86	Manhole/utility cover	010
92	Pothole/edge of carriageway deterioration	011
94	Pothole/patching	012

99	Fracturing	013
101-137	Edge of carriageway deterioration/potholing and fracturing	014-015
143	Fracturing	016
158	Fracturing	017
171-182	Edge of carriageway deterioration	018-019
197	Speed bump/ramp	020
207	Fracturing	021
232	Fracturing	022
237-259	Fracturing	023-024
279	Fracturing	025
323	Fracturing	026
345-350	Edge of carriageway deterioration	027
359	Fracturing	028
389	Speed bump/ramp and patching	029
396	Fracturing/minor drop in surfacing	030
439	Fracturing	031
459	Fracturing	032
464	Pothole	033
469	Fracturing	034
481	Fracturing	035
493	Fracturing on speed bump/ramp	036
501-516	Fracturing	037-038
562	Fracturing	039
575	Speed bump/ramp and patching	040
576-589	Fracturing	041-042
614	Edge of carriageway deterioration	043
681	Fracturing	044
712	Fracturing	045
753	Speed bump/ramp	046
805-821	Fracturing	047-048
827	Fracturing	049
832	Paint faded at Mopes Lane/Cricklade Road junction	050
838	Fracturing/patching/faded paint at Mopes Lane/Cricklade Road junction	051-052

Figures

A3
ORIGINAL
PLOT SIZE



NOTES

Key

- Site Location
- Agreed Highway Condition Survey Extent

Rev	Date	Details	Drawn by	Checked by	Approved by

Bristol
Cambridge
London
Oxford
Welwyn Garden City

tpa Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT:
Spring Dev 08 Limited

PROJECT:
Purton Landfill Solar, Wiltshire

TITLE:
Pre-Construction Highway Condition Survey Extent

STATUS:
FOR INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	29/06/23	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Figure 2.1	-

APPENDIX A

	001	002	003
Pre-Construction			
Post-Construction			

	004	005	006
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 001 – 006

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	007	008	009
Pre-Construction			
Post-Construction			

	010	011	012
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 007 – 012

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	013	014	015
Pre-Construction			
Post-Construction			

	016	017	018
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 013 – 018

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	019	020	021
Pre-Construction			
Post-Construction			

	022	023	024
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 019 – 024

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	025	026	027
Pre-Construction			
Post-Construction			

	028	029	030
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

tpa
Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 025 – 030

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	031	032	033
Pre-Construction			
Post-Construction			

	034	035	036
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 031 – 036

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	037	038	039
Pre-Construction			
Post-Construction			

	040	041	042
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 037 – 042

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	043	044	045
Pre-Construction			
Post-Construction			
	046	**047**	**048**
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

2E King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 043 – 048

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	049	050	051
Pre-Construction			
Post-Construction			

	052	053	054
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 049 – 054

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	055	056	057
Pre-Construction			
Post-Construction			

	058	059	060
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 055 – 060

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	061	062	063
Pre-Construction			
Post-Construction			
	064	**065**	**066**
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

2E King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 061 – 066

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

	067	**068**	**069**
Pre-Construction			
Post-Construction			
	070	**071**	**072**
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Westbound Condition Survey, Photos 067 – 072

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix A	-

APPENDIX B

A3
ORIGINAL
PLOT SIZE



W E S

INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

tpa
Transport Planning Associates

CLIENT:
Spring Dev 08 Limited

PROJECT:
Purton Landfill, Solar, Wiltshire

TITLE:
Westbound Condition Survey Defect and Photo Locations

STATUS:
INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix B	-

A3
ORIGINAL
PLOT SIZE



INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Westbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix B	-

A3
ORIGINAL
PLOT SIZE



W E S

INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Westbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix B	-

A3
ORIGINAL
PLOT SIZE



INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Westbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix B	-

A3
ORIGINAL
PLOT SIZE



INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

tpa
Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Westbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix B	-

A3
ORIGINAL
PLOT SIZE



W E S

INDICATIVE

Reproduced from Ordnance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Westbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix B	-

APPENDIX C

	001	002	003
Pre-Construction			
Post-Construction			

	004	005	006
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 001 – 006

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	007	008	009
Pre-Construction			
Post-Construction			

	010	011	012
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa
Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 007 – 012

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	013	014	015
Pre-Construction			
Post-Construction			

	016	017	018
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 013 – 018

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	019	020	021
Pre-Construction			
Post-Construction			

	022	023	024
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 019 – 024

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	025	026	027
Pre-Construction			
Post-Construction			

	028	029	030
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 025 – 030

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	031	032	033
Pre-Construction			
Post-Construction			

	034	035	036
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

tpa
Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 031 – 036

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	037	038	039
Pre-Construction			
Post-Construction			

	040	041	042
Pre-Construction			
Post-Construction			

Reproduced from Ordnance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

tpa
Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 037 – 042

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	043	044	045
Pre-Construction			
Post-Construction			

	046	047	048
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 043 – 048

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

	049	050	051
Pre-Construction			
Post-Construction			
	052		
Pre-Construction			
Post-Construction			

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

tpa
Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill Solar, Wiltshire

TITLE: Eastbound Condition Survey, Photos 049 – 052

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
N/A	June 2023	AG	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix C	-

APPENDIX D

A3
ORIGINAL
PLOT SIZE



INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Eastbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix D	-

A3
ORIGINAL
PLOT SIZE



INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Eastbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix D	-

A3
ORIGINAL
PLOT SIZE



W E S

INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Eastbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix D	-

A3
ORIGINAL
PLOT SIZE



W E S

INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

tpa Transport Planning Associates

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Eastbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix D	-

A3
ORIGINAL
PLOT SIZE



W E S

INDICATIVE

Reproduced from Ordinance Survey Superplan Data with the permission of The Controller of Her Majesty's Stationrey Office, Crown Copyright – Licence No. AL 100034021

NOTES:

Rev	Date	Details	Drawn by	Checked by	Approved by
-	-	-	-	-	-

Bristol
Cambridge
London
Manchester
Oxford
Welwyn Garden City

25 King Street
Bristol
BS1 4PB

0117 925 9400
www.tpa.uk.com

tpa Transport Planning Associates

CLIENT: Spring Dev 08 Limited

PROJECT: Purton Landfill, Solar, Wiltshire

TITLE: Eastbound Condition Survey Defect and Photo Locations

STATUS: INFORMATION

SCALE:	DATE:	DRAWN:	CHECKED:	APPROVED:
NTS	June 2023	KVT	RR	JD

JOB NO:	DRAWING NO:	REVISION:
2304-036	Appendix D	-