

x1 Acacia tree to dismantle to ground level as now having lost two large lower limbs leaves tree as risk of failing
x1 Acacia tree to reduce lower branches by up to 3m and clean up broken storm damaged branch
x1 Conifer to be felled to ground level
x1 Conifer to be felled to ground level
Restaurants
Hotels
Things to do
Museums
Transport
Chemists
ATMs
Round Windows
Temporarily closed
F F Services
Cuffs Ln
Park Rd
Queens Rd
Layers
Google
Imagery ©2023 Infoterra Ltd & Bluesky, Map data ©2023
United Kingdom
Terms
Privacy
Send feedback
10 m