COPYRIGHT



REPAIR DETAIL 01
INFILL NEXT TO LIFT AT GROUND FLOOR LEVEL
(1:50)



REPAIR DETAIL 02
INFILL NEXT TO LIFT AT MEZZANINE LEVEL
(1:50)



REPAIR DETAIL 03
MEZZANINE FLOOR PART PLAN
(1:20)

Ceiling joists omitted for clarity.

0m 1m 2m 3m 4m 5m
SCALE BAR
(1:50)

0m 0.5m 1m 1.5m 2m
SCALE BAR
(1:20)

notes

1. This drawing is to be read in conjunction with all relevant Architect's and Engineer's drawings and the specification.

-	01.04.21	Issued for Information.	PS

job
TOTTENHAM HOUSE, WILTSHIRE

title
MAIN HOUSE
MEZZANINE AND GROUND FLOOR TIMBER REPAIRS

drawn: RG
checked: PS
date: MAR'21
scale (original - A1): AS SHOWN

Alan Baxter
75 Cowcross Street London EC1M 6EL
tel 020 7250 1555
email aba@alanbaxter.co.uk
www.alanbaxter.co.uk

ABA Job No. 1896/10

drg. no. **THB001-ABA-XX-XX-SK-S-2059**
rev. -

Alan Baxter Ltd is a limited company, registered in England and Wales, number 06630598. Reg.stered office as above.