Still Green
Arboriculture Services

PLANNED PRUNING WORKS TO TREES COVERED BY A TPO

RE: 12 WILLOWBANK, CHIPPENHAM, WILTS, SN14 6QG




FIG 1: T1 mature sycamore on left and T2 ash on the right



FIG 2: T1 sycamore towering over T2

T1 is a mature sycamore (*Acer pseudoplatanus*) with an approx. height of 14m, standing next to a grafted cultivated ash tree (*Fraxinus spp*) which has an approx. height of 7m. Both trees are located in a modestly sized garden area at the front of the aforementioned property. T2 has a one-sided crown and is supressed by it's more dominant neighbour. T1 and T2 have previously had their crowns reduced approx. 4-5 years ago. It is proposed that the same works are repeated with their crowns being reduced to where they were previously done. This is proposed in order to keep the trees at a manageable size for their location. This will result in T1's crown being reduced by approx. 4-5m and T2's crown being reduced by approx. 2-3m.

Simon Newman
Dip Arb L4 (ABC) TechArborA

Thursday, 07 September 2023