**23_107**

60A Winchester Street, Salisbury




Photos showing roof draining under steel roof structure to valley gutter





60

60A

VALLEY GUTTER

Access Hatch

RWP

Detail Plan of junction of valley gutter with existing rainwater pipe



Timber stud insulated fabric to main building

Water run off below the steel angle to roof truss to valley gutter




60

STRUCTURE OVER

VOID

60A

RWP OUTLET

Existing RWP in void between 60A and 60

Plan of infill roof over 60A, between 60 & 62 @ 1:50




© Copyright 2023

SCRACE ARCHITECTS

01722 658048
info@scracearchitects.co.uk

**sk003 - Listed Building Consent**

Existing Roof Drainage / Photos - 1:50 @ A3

Scale 1:100

0 1 2 3 4 5 10