AYERS FORESTRY LIMITED

TREE SURVEY SCHEDULE

Client: Chris Whealey-Hubbard

Site: Boyton Farm - Ginger Piggery


Date of Survey: 2nd November 2023

Surveyor: Bill Ayers

Weather: Overcast & rain

Tagged: No

Tree ID	Common Name	Stems	Height (m)	Stem Dia (mm)	Spread Radius (m)	Maturity	Overall	Branches	Leaf/Buds	Roots	Stem	Work Category	Priority	Comment
1	Lime	1	17	500	4	Mature	Poor	Apical die back;Minor dead wood;Major dead wood	25% dead / absent	Fungus or decay	Bark wounds; Fungus or decay; Cavities	Fell	High	Old pollard with significant decay in base of stem. Probably too much decay to support another pollard. Fell within 9mths
2	Lime	1	20	525	6	Mature	Good	Minor dead wood	Normal	No visual defects	No visual defect	Monitor		All good
3	Ash	4	19	450	9	Mature	Fair	Minor dead wood	25% dead / absent;	No visual defects	Ivy covered; Epicormic growths	Fell	High	Heavily seeding and epicormic growth. Dropping branches. Over car park and path. Fell within 9mths. Leave sycamore
4	Sycamore	1	21	500	9	Mature	Good	No visual defects	Normal	No visual defects	No visual defect	Monitor		Monitor for deadwood in crown
5	Sycamore	1	21	500	9	Mature	Good	No visual defects	Normal	No visual defects	No visual defect	Monitor		Monitor for deadwood in crown
6	Ash	1	24	957	10	Mature	Good	Minor dead wood;Old pruning wounds;Epicormic growths	Normal	No visual defects	No visual defect	Monitor		Large ash supported by surrounding trees. Monitor for ADB
7	Ash	1	22	425	6	Mature	Fair	Apical die back;Minor dead wood;Major dead wood	25% dead / absent	Fungus or decay	Fungus or decay; Cavities	Fell	High	Stool grown ash, was two large stems , one was felled. Decay has been introduced to base of stem.
8	Sycamore	1	22	500	9	Mature	Good	No visual defects	Normal	No visual defects	No visual defect	Monitor		Monitor for deadwood in crown
9	Sycamore	1	21	500	9	Mature	Good	No visual defects	Normal	No visual defects	No visual defect	Monitor		Monitor for deadwood in crown



Boyton Farms

The Ginger Piggery

SCALE : 1 : 1000 @ A4

DATE : 10/11/2023

N

Ayers Forestry Limited
Woodland Management & Consultancy

Map data shown may contain Ordnance Survey ® products supplied by Pear Technology Services Ltd; Email: info@peartechnology.co.uk
© Crown Copyright and database rights from date shown above
Ordnance Survey ® licence number 100023148