LEGEND

1. Brick.
2. Stone surround - painted.
3. Stone central mullion - painted.
4. Projecting stone cill - painted.
5. Timber frame to window.
6. Single glazed fixed light.
7. Single glazed opening light.
8. Slimlite double glazed fixed light.
9. Slimlite double glazed unit to opening light, bead fixed.
10. Projecting drip bead to bottom of glazing unit.
11. Projecting painted timber cill rebated into (repaired) cill/stool of frame.
12. All paint removed from stone surround and mullion.



Existing window elevation.



Proposed window elevation.



Existing section at base of window.
Scale 1:10



Proposed section at base of window.
Scale 1: 10.

Copyright: Vallis Architecture Ltd. Registered in the UK, No. 11361587.

Do not scale from this drawing. Responsibility will not be accepted for errors made by others in scaling from this drawing. Use figured dimensions only. All critical dimensions should be verified on site.

Scale 1:20 at A3

0 0.2 0.4 0.6 1 2m

LBC SUBMISSION

Issue	Date	Revision description
A	2023-04-20	Pre-application submission.

Project
The Angel Mill, Edward St., Westbury.

Client
Sandoes chartered surveyors.

Project no.
2301

Drawing no.
3 305

Revision
A

Drawing Title
Ex & pro window repair + refurbishment

Date
2023-10-23

Scale
1:20 at A3

Vallis **A**rchitecture Ltd., 1 Styles Avenue, Frome, Somerset BA11 5JN.
07967 684 690 giles@vallisarchitecture.co.uk