

**Design detail: Window replacement, The House, Salsibury Street**

**Exisiting North Elevation**



- The kitchen window is the bottom left
- 30 pane partial sash wndow
- Assumed to have been replaced by a window taken from another property
- The central timber mullion is significantly rotten, neccesitating replacement

**Proposed North Elevation**



- 12 pane casement window
- Size of the panes are in keeping with the style of the original windows
- Casement style would match the existing lounge window to the west/right of the door.
- Propose to use a duplex type double glazed unit not exceeding 14mm