
Current Flood Defences centered on NGR ST 95686 79168 Created 24/02/2023 Ref: 298539-WX



Environment Agency

Scale: 1:9,009

N
W E
S

Legend

Defences

- Barrier Beach
- Beach
- Bridge Abutment
- Cliff
- Demountable Defence
- Dunes
- Embankment
- Engineered High Ground
- Flood Gate
- Natural High Ground
- Promenade
- Quay
- Spillway
- Wall

This data has been extracted from the Asset Information Management System (AIMS OM) which was created to draw various data sources into one database and has been populated with information of varying quality.

© Environment Agency copyright and / or database rights 2022. All rights reserved. © Crown Copyright and database right 2022. Ordnance Survey licence number 100024198.

Contact Us: National Customer Contact Centre, PO Box 544, Rotherham, S60 1BY. Tel: 03708 506 506 (Mon-Fri 8-6). Email: enquiries@environment-agency.gov.uk

Product 4 - AIMS Information **298539-WX** **Date:** **24/02/2023**

Map Ref	Asset ID	Asset Type	Right or left bank	Asset Description	Approx length (m)	Actual fluvial downstream crest level (mAOD)	Actual fluvial downstream crest level accuracy	Actual fluvial upstream crest level (mAOD)	Actual fluvial upstream crest level accuracy	Actual fluvial coastal crest level (mAOD)	Actual fluvial coastal crest level accuracy	NGR	Most recent inspection	Overall condition
1	109014	Natural High Ground	Right	Natural Bank	2617.83	DNR	DNR	DNR	DNR	DNR	DNR	ST94677901	09/06/2020	3 - Fair
2	161259	Natural High Ground	Left	Natural Bank	169.65	DNR	DNR	DNR	DNR	DNR	DNR	ST95557913	28/10/2021	3 - Fair
3	39946	Natural High Ground	Left	Natural Bank	102.34	DNR	DNR	DNR	DNR	DNR	DNR	ST95397921	09/06/2020	3 - Fair
4	40411	Natural High Ground	Right	Sheet Piling	45.50	DNR	DNR	DNR	DNR	DNR	DNR	ST95467922	28/10/2021	3 - Fair
5	40412	Natural High Ground	Right	Natural Bank	1689.43	DNR	DNR	DNR	DNR	DNR	DNR	ST95278001	28/10/2021	3 - Fair
6	4557	Natural High Ground	Right	Natural Bank	73.78	DNR	DNR	DNR	DNR	DNR	DNR	ST95637902	28/10/2021	2 - Good
7	4558	Natural High Ground	Right	Natural Bank	56.71	DNR	DNR	DNR	DNR	DNR	DNR	ST95427925	28/10/2021	3 - Fair
8	4744	Natural High Ground	Left	Natural Bank	77.39	DNR	DNR	DNR	DNR	DNR	DNR	ST95657903	28/10/2021	2 - Good
9	4778	Natural High Ground	Left	Natural Bank	103.68	DNR	DNR	DNR	DNR	DNR	DNR	ST95517921	28/10/2021	2 - Good
10	57886	Natural High Ground	Right	Natural Bank	205.60	DNR	DNR	DNR	DNR	DNR	DNR	ST95487915	28/10/2021	3 - Fair
11	57887	Natural High Ground	Right	Natural Bank	101.04	DNR	DNR	DNR	DNR	DNR	DNR	ST95387921	09/06/2020	3 - Fair
12	78800	Natural High Ground	Right	Natural Bank	1832.17	DNR	DNR	DNR	DNR	DNR	DNR	ST95847816	26/08/2021	3 - Fair
13	78802	Natural High Ground	Left	Sheet piles, changing to Natural Bank d/s of structure	1904.12	DNR	DNR	DNR	DNR	DNR	DNR	ST95877816	26/08/2021	3 - Fair
14	80515	Natural High Ground	Left	Natural Bank	1668.76	DNR	DNR	DNR	DNR	DNR	DNR	ST9538680056	28/10/2021	3 - Fair
15	89318	Natural High Ground	Left	Natural Bank	2656.82	DNR	DNR	DNR	DNR	DNR	DNR	ST94637901	09/06/2020	3 - Fair

Notes
* Overall Condition has been taken from the most recent inspection
* Inspections are of a purely visual nature and do not necessarily reflect the true condition of the asset
* Condition: 1 = very good, Condtion 2 = good, Condition 3 = fair, Condition 4 = poor, Condition 5 = very poor
* Crest level accuracy: 1 = ± 0.01 to 0.05m, 2 = ± 0.05 to 0.15m, 3 = ± 0.15 to 0.75m, 4 = ± 0.75 or greater
* DNR = data not recorded