Listed Consent Application

Rose Cottage, 44, Corton, Warminster, BA12 0SZ:

PL/2023/05574

Detailed Annotated Photos

These images will show the extent of the works to be undertaken.

Figure 1 below shows the front of the cottage where proposed works are to be undertaken. The entirety of the paint on the front of the building will be removed by a specialist company using appropriate and sensitive methods. The paint on the windows and window frames will not be removed.



Figure 1: Rose Cottage Front of House

Figure 2 below shows the detail of exactly which areas of paintwork on the front of the property are to be removed. The entirety of the front of the property will be done. The cottage is terraced so there are no sides, and the reverse of the property will not be treated as there is no paint there to be removed.



Figure 2: Annotated photo showing extent of works

Figure 3 below shows the existing condition of the paintwork. It is in a poor condition, with paint flaking off of the underlying structure. This work will ensure it is treated well and the historic fabric is undamaged, and will return the cottage to its original condition, improving the aesthetic and historical value of the property and surrounding area.



Figure 3: Existing paintwork condition