Window Schedule

Item	Drawing #	Elevation	Location	Description	Type
WG01	300	North East	Boot room	Unauthorised single glazed casement to be replaced with double glazed casements	**B**
WG02	301	North East	Kitchen	Unauthorised double glazed casement. Seeking retrospective consent.	**A**
WG03	302	North East	Kitchen	Unauthorised double glazed sash window. Seeking retrospective consent.	**A**
WG04	303	North East	Living room	Proposed repairs and refurbishment only	**D**
WG06	304	North East	Drawing Room	Proposed repairs and refurbishment only	**D**
WG07	305	South West	Drawing Room	Proposed repairs and refurbishment only	**D**
WG09	306	South West	Living room	Proposed repairs and refurbishment only	**D**
WG12	307	South East	Play room	Proposed replacement window	**C**
WG15	308	South West	Boot room	Unauthorised single glazed casement, proposal to be replaced with double glazed casements	**B**
WG16	309	North West	WC casement	Unauthorised single glazed casement, proposal to be replaced with double glazed casements	**B**
WG18	310	North West	Boot room	Unauthorised single glazed casement, proposal to be replaced with double glazed casements	**B**
WG19	311	North West	Boot room	Unauthorised single glazed casement, proposal to be replaced with double glazed casements	**B**
WF25	312	Front/ North	Ensuite sash	Unauthorised double glazed casement. Seeking retrospective consent.	**A**
WF26	313	North East	Landing	Proposed replacement window	**C**
WF27	314	North East	Landing	Proposed replacement window	**C**
WF28	315	South East	Bathroom	Proposed replacement window	**C**
WF29	316	South West	Bedroom	Proposed repairs and refurbishment only	**D**
WF30	317	South West	Bedroom	Proposed repairs and refurbishment only	**D**
WF31	318	South West	Bedroom	Proposed repairs and refurbishment only	**D**
WF32	319	South West	Bedroom	Proposed repairs and refurbishment only	**D**
WF33	320	South East	Bedroom	Unauthorised double glazed casement. Seeking retrospective consent. Bars to be reinstated	**A**
WG34	321	South West	Bedroom	Unauthorised double glazed sash window and opening. Seeking retrospective consent.	**A**
WF35	322	North West	Bedroom	Unauthorised double glazed casement. Seeking retrospective consent. Bars to be reinstated	**A**
WS40	323	South East	Attic	Unauthorised double glazed sash window and opening. Seeking retrospective consent.	**A**
WS41	324	North West	Attic	Proposed replacement window	**A**

A Existing unauthorised window seeking retrospective consent

B Existing unauthorised window seeking proposed consent for new replacement window

C Original window seeking proposed consent for replacement window

D Orginal windows seeking proposed consent for refurbishment and repairs only

PLANNING & LISTED BUILDING CONSENT Notes

A. All Drawings to be read in conjunction with supporting Design & Heritage Statement
B. Do not scale from this drawing use figured dimensions only. All dimensions are to be checked on site.
C. Contractor to report any discrepancies, drawing errors and omissions to Chalk Architects immeadiatley
D. All structural elements to Structural Engineer's details and specifications
E. All work subject to Listed Building Consents & Planning Approval including conditions issued by Local Planning Authority
F. All work to comply with guidance within relevant UK Building Regulations Approved Documents
G. All work subject to the Party Wall Act etc 1996.

Revision: Date: Reason:

LBC

Manor Farmhouse, Windows only [SN10 5UE] **22-03.01W-200**

Window Schedule

Scale:	Paper size:	Date:	Drawn by:	Checked by
N/A	A3	22/08/2023	JM	JM

Chalk.

Chartered Practice No.20035647 www.chalkarchitects.co.uk hello@chalkarchitects.co.uk
© 2023. All Rights Reserved