clarkebond

Validation of remedial capping for gardens and areas of landscaping

Site	Boreham Road, Warminster, BA12 9JP		
Developer	Backhouse Housing Ltd.		
NHBC Project No.	SNIN 0006141094		
Plot(s) number	Plot 7-10. One elongated trench excavated across garden boundaries to check consistency.		
Tested by	M Briggs	**Date tested**	23/06/2023
Area of use	Garden.		
Topsoil description	Grey brown loamy sand.		
Topsoil origin	London Rock Supplies Ltd.		
Topsoil certificate attached	YES – Tim O'Hare assessment, Ref TOHA/22/7764/SS.		
Subsoil description	Orange brown/cream clayey cobbley gravel, as dug subsoil.		
Subsoil origin	Land West of Silver Street, Midsomer Norton.		
Subsoil certificate attached	YES – Extract from Ruddleston geotechnical report Ref TN/SR/20188/GICAR, lab testing undertaken by i2 Labs.		
Remedial requirements	Capping soil to be certified suitable for use and 600mm thick.		

Depth of soil cap measured	700mm	**Textile present**	Yes	**Passed**	YES



View of completed garden strip to rear of Plot 7-11.



Location of inspection pit across plot 7-10 boundaries.

Clarkebond (UK) Limited
Registered in England & Wales No 7775761
Registered Office: 129 Cumberland Road, Bristol, BS1 6UY

Bristol Property INCLUSION CHARTER

ISO Certificate No
9001 228798
14001 228799
19650-2 229766

British Assessment Bureau
UKAS MANAGEMENT SYSTEMS 8289
ISO 9001 QUALITY MANAGEMENT

clarkebond

	
Topsoil detail.	View of full thickness of capping, with membrane visible at base of pit.