clarkebond

Validation of remedial capping for gardens and areas of landscaping

Site	Boreham Road, Warminster, BA12 9JP		
Developer	Backhouse Housing Ltd.		
NHBC Project No.	SNIN 0006141094		
Plot(s) number	Plot 11.		
Tested by	M Briggs	**Date tested**	23/06/2023
Area of use	Garden.		
Topsoil description	Grey brown loamy sand.		
Topsoil origin	London Rock Supplies Ltd.		
Topsoil certificate attached	YES – Tim O'Hare assessment, Ref TOHA/22/7764/SS.		
Subsoil description	Orange brown/cream clayey cobbley gravel, as dug subsoil.		
Subsoil origin	Land West of Silver Street, Midsomer Norton.		
Subsoil certificate attached	YES – Extract from Ruddleston geotechnical report Ref TN/SR/20188/GICAR, lab testing undertaken by i2 Labs.		
Remedial requirements	Capping soil to be certified suitable for use and 600mm thick.		

Depth of soil cap measured	600mm	**Textile present**	Yes	**Passed**	YES



View of completed garden strip to rear of Plot 7-11.



Plot 11 topsoil detail.

clarkebond

	
View of full thickness of capping.	View of membrane at base of pit.