PROPERTY ASSURANCE
Giving our all

SITE INVESTIGATION
FACTUAL REPORT

Report No:	SI-439692
Client:	Sedgwick International UK - Morley
Site:	34 Southwood Road Wiltshire
Client Ref:	9473216
Date of Visit:	11/3/2022

ISO 9001 REGISTERED FIRM | ISO 14001 REGISTERED FIRM | OHSAS 18001 REGISTERED FIRM | Link-up Qualified via Audit | SAFEcontractor APPROVED | CHAS Accredited Contractor www.chas.gov.uk | constructionline

Unit E2 First Floor Suite, Boundary Court
Willow Farm Business Park, Castle Donington
Leicestershire, DE74 2NN

☎ 0843 2272362
✉ enquiries@cet-uk.com
💻 www.cet-uk.com

CET is the trading name of CET Structures Ltd
Registered in England No. 02527130

EPSL
Independent Scientific Analysis

European Plant Science Laboratory

Construction Testing Solutions
4 Oak Spinney Park
Ratby Lane
Leicester Forest East
Leicestershire
LE3 3AW

Intec
Parc Menai, Bangor,
Gwynedd, North Wales
LL57 4FG
Tel: 01248 672652
Fax: 01248 672601

ROOT IDENTIFICATION

34 Southwood Road, Trowbridge

Client Reference: 439692
Report Date: 16 March 2022
Our Ref: R44780

Sub Sample	Species Identified		Root Diameter	Starch
TP1:				
USF	*Fraxinus* spp.	1	3 mm	Low
BH1:				
1.8m	*Fraxinus* spp.	2	<1 mm	Low

Comments:

1 - Plus 4 others also identified as *Fraxinus* spp.
2 - Plus 1 other also identified as *Fraxinus* spp.

Fraxinus spp. include common ash.

Signed: G S Turner

Unless we are otherwise instructed in writing, the above sample material will normally be disposed of 6 years after the date of this report.