TUCKER JOINERY


CLS diagrams

Client **Mrs Catherine**

Job **1 number Hardwood conservation sash window**

Ref **33 St Matins**

1 X Sliding Sash - SS1




Job number	Job reference		
lee5982	33 St Matins	13:38 2-01-24	6 of 10

CAD 2, 4, 3, 5 (59629)


TUCKER JOINERY

CLS diagrams

SS1
Top sliding sash



SS1
Bottom sliding sash



Job number	Job reference		
lee5982	33 St Matins	13:38 2-01-24	7 of 10