25 West Street – Wilton. Photographs showing current windows



Front elevation of house showing all 3 windows to be replaced, please note that this building was listed after extensive alterations (pebble dash/ windows)

25 West Street – Wilton. Photographs showing current windows



East elevation – Kitchen showing crittall windows in poor state of repair to be replaced

25 West Street – Wilton. Photographs showing current windows



West elevation bathroom window, currently swing opening to be replaced with French casement window with appropriate bathroom glass to provide privacy(you can see the neighbours windows in the refection and they are able to see directly into the bathroom)

25 West Street – Wilton. Photographs showing current windows



West elevation ground floor window, currently swing opening to be replaced with French casement window.

25 West Street – Wilton. Photographs showing current windows



South Elevation showing bedroom window (sash window) to be replaced with same design.

25 West Street – Wilton. Photographs showing current windows

O/A Dim 1600mm x 1230mm



Front room

O/A Dim 1230mm x 1030mm



Lounge 1

O/A Dim 970mm x 1330mm



Lounge 2

Liniar Sculpt Flush Casement

Golden Oak Style: 52

O/A Dim 950mm x 870mm



Kitchen Left

Liniar Sculpt Flush Casement

Golden Oak Style: 24

O/A Dim 970mm x 985mm



Kitchen right

Liniar Sculpt Flush Casement

Golden Oak Style:

O/A Dim 985mm x 815mm



Bathroom

Liniar Sculpt Flush Casement

Golden Oak Style: 62

O/A Dim 1620mm x 1030mm



Front bedroom

Liniar Sculpt Flush Casement

Golden Oak Style: 52

O/A Dim 1020mm x 1020mm



Top room