

Appendix I – photo's of bat and bird mitigation, compensation and enhancement

Conholt Park, Conholt Lane, Chute, Andover, SP11 9HA

B1 – bat loft,
access points,
internal bat boxes,
bat access tiles

















B2 – bat loft







B3 – cellar retained
with new access
point





B4 – bat loft, bat
access tiles









B5 - bat loft, bat
access tiles





	 A close-up photograph of a concrete wall. A rectangular opening is visible, showing wooden framing inside. The concrete is light grey and appears to be under construction or repair.
New 3 bay garages	 A photograph of a new 3-bay garage. The structure has a red tiled roof and concrete pillars. A person in an orange safety vest is visible on the left, and a dark van is parked on the right. The sky is blue with white clouds.







B13/14 – gable
access





B15 – barn owl box
and access





B18- loft and
access point





B20 – loft and
access tiles







B24 – verge access
points retained





Bat boxes on trees
(all in the
woodland adjacent
to B4)









	
House martin towers (now removed as of September 2025 now B1 is available again for nesting in 2026. Towers were removed following a nesting bird check by Arbtech)	



	
Swallow shelters	



B26 – swallow cups
and access





B27- swallow cups
and access







B28– swallow cups
and access



