

St Boniface House, Warminster School, Church St BA12 8PQ
Photos of fire damage



Photo (i) – elevation with oriel window

St Boniface House, Warminster School, Church St BA12 8PQ
Photos of fire damage



Photo (ii) – close up of damage to oriel window



Photo (iii) – internal damage

St Boniface House, Warminster School, Church St BA12 8PQ
Photos of fire damage



Photo (iv) – damage to timber box frame

St Boniface House, Warminster School, Church St BA12 8PQ
Photos of fire damage



Photo (v) – timber panelling beneath window