

Photosheet: Barter's Farm Horticultural Nursery



Photos 1: View facing north of the eastern side of Barter's Horticultural yard.
NB. customers to the adjacent nursery do not have access to this area.

Key

1. 2 No. Portacabin Offices currently stored in their proposed permanent position. NB. these units are not currently in use.
2. Recently erected Double Polytunnel A. NB. not yet in use as second double polytunnel immediately to the north is currently being erected.
3. Staff WC block sited in its proposed permanent position NB. Newland Homes are contractually obliged to provide a service trench, including a foul drainage connection to their recently permitted Phase 2 development on the western side of the existing horticultural site (LPA Ref: PL/2023/05349)



Photo 3: Double Polytunnel A. Construction nearing completion as the date of photograph (14th December 2025)



Photo 2: The second Double Polytunnel B currently under construction (NB. date of photograph 14th December 2025)

Photosheet: Barter's Horticultural Nursery



Photos 4: 2 No. pre-fabricated buildings proposed to be used for administration and welfare by horticultural staff have been placed in situ pending commissioning/occupation.

Photosheet: Barters Horticultural Nursery



Photos 5-8: photographs of each elevation of the proposed staff WC Block. NB. this unit is not yet in use but is sited in its proposed permanent position.