

East Facing door.



Replacement of existing concrete step with a bullnose step in Chilmark stone or similar local



Repair to rot and replacement where necessary of existing door frame with painted hardwood – like for like.

South Facing original front door.



Replacement of existing concrete step with a bullnose step in Chilmark stone or similar local



Repair and like for like replacement of South Facing porch.



Existing rot



Existing rot to posts



Example style of staddlestone footing

Proposed sandstone post staddle stone at base of uprights to prevent future rot.

Granite Setts to delineate boundary/driveway



Installation of double row of granite setts along eastern boundary to delineate boundary and keep gravel from spilling into road.



Granite setts to be similar in size and colour to these.