

A - Cap

B - Upper Needle

C - Middle Needle

D - Lower Needle

E - 3rd Stage Base

F - 2nd Stage Base

G - 1st Stage Base

H - 3rd Stage Plinth

I - 2nd Stage Plinth

J - 1st Stage Plinth

NORTH-EAST ELEVATION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106

y

y

y

lightning conductor rod

lightning conductor band

lightning conductor band

North

East

Key

x replace dressed stone ashlar quoins/mouldings

y repair to partially-decayed stone using gault clay tiles laid horizontally in lime-based mortar

y1 repair to partially-decayed stone using gault clay tile laid vertically (on edge)

z replaced stone quoin (2024)

rake out and re-point facing masonry

take down and re-build facing masonry

re-set existing stone

ANDREW TOWNSEND ARCHITECTS

HISTORIC BUILDINGS CONSULTANTS

MARLBOROUGH HOUSE 2 BROMSGROVE FARINGDON OXON SN7 7JQ
Tel 01367 242639 Email info@andrewtownsend.co.uk
www.andrewtownsend.co.uk

project

Proposed repairs to
The Lansdowne Monument, Cherhill Down, Wilts

for The National Trust

drawing

Elevations

as proposed

date

Sep 2025

scale

1:100

Drawing original is A3 size


drg. no.

1374: WD06

rev.

-

Metres



All dimensions shown are nominal and are to be checked on site by the contractor for prices and construction purposes.